

CHANGE LOG

FIRMWARE

**S100C**

Version 2



**Serra Soldadura, S.A.U.**

Polígono Industrial Zona Franca  
Calle D, nº 29  
08040 BARCELONA (España)

**Teléfono:** +34 93 261 71 00  
**Asistencia Técnica:** +34 93 261 71 00 Ext.: 17200  
**Internet:** <http://www.serrasold.com>  
**Descargas:** <http://serratron.serrasold.com>

---

The information contained in this document may be changed without prior warning.

No part of this manual may be reproduced or distributed in any way nor by any means either electronically or mechanically without written permission from SERRA Soldadura S.A.U.

© 2024 SERRA soldadura, S.A.U.

---

# CHANGE LOG

<b>Hardware version HiRes (50kA)</b>				
Date	Firmware version	Manual version	CPC version	Description
25/06/2024	2.01.00	<b>2.0</b> 2024/25	3.21	Deployment version 2 – extended PLC
01/07/2024	2.01.01	“	“	Data conversion v1 to v2 optimized
08/07/2024	2.01.02	“	“	New devices startup optimized
03/09/2024	“	<b>2.0</b> 2024/36	“	Pdf file data correction
04/09/2024	2.01.03	“	“	Corrects error 550 at startup PNET board
12/09/2024	2.01.04	<b>2.0</b> 2024/37	“	Review startup PNET & EthIP boards. Manual correction.
28/10/2024	“	<b>2.0</b> 2024/44	“	Corrected error 91 index 6 solution proposal

<b>Hardware version Std (100kA)</b>				
Date	Firmware version	Manual version	CPC version	Description
25/06/2024	2.02.00	<b>2.0</b> 2024/25	3.21	Deployment version 2 – extended PLC
01/07/2024	2.02.01	“	“	Data conversion v1 to v2 optimized
08/07/2024	2.02.02	“	“	New devices startup optimized
03/09/2024	“	<b>2.0</b> 2024/36	“	Pdf file data correction
04/09/2024	2.02.03	“	“	Corrects error 550 at startup PNET board
12/09/2024	2.02.04	<b>2.0</b> 2024/37	“	Review startup PNET & EthIP boards. Manual correction.
28/10/2024	“	<b>2.0</b> 2024/44	“	Corrected error 91 index 6 solution proposal